DB820 hp TIJ2.5 Bulk Solvent Ink Supply System





400ml of ink more than ten times the ink cartridge in the printhead itself



A cartridge can process a throughout volume of up to 1.2 litres (3 bulk ink cartridges) before it needs to be replaced. The frequency of ink changing is reduced significantly by using the DB820.

Easily operate ink automatically prime by a small panel completely avoid mess up inkjet printer working field.



The new pump ink system allows more freedom in positioning the bulk ink cartridge. A new removable print cartridge connector ensures no downtime occurs at the bulk ink cartridge replaced.



28cm

The alarm beacon indicates the bulk ink system running status

The yellow light alerts operator ink is in low level, replace a new bulk ink cartridge is required, or then red light up alone with siren goes off is represents the system breaks working. Green represents the bulk ink system is in working smoothly.

Dotjet Inc.



Please contact us